A-DRY SERIES ADSORPTION DRYERS

pressure range	4 to 16 bar
temperature oper. range	+1,5 to +45 °C
pressure dew points	-25 °C /-40 °C /-70 °C
flow rates	6 Nm³/h to 105 Nm³/h



APPLICATIONS

• compressed air systems

ADVANTAGES

- Wide range of products to fit your need.
- Robust and intuitive ready to use controller.
- Simple assembly and disassembly.
- Fast and reliable servicing.
- Adsorbent in cartridges
- Standard version includes coalescing pre-filter and particle afterfilter



DESCRIPTION

A-DRY desiccant adsorption dryer has been designed to separate water moisture from compressed air thus reducing the dew point in the system. A-DRY is a range of products offering our customers a wide array of dried air solutions with volumetric flow rates ranging from 6 Nm³/h.

An innovative new design of A-DRY adsorption driers, developed with consideration of our customers, enables fast and reliable installation, use and servicing. Installation is simple with our ready to use controller while minimising the number of parts and motions required for assembly and disassembly makes servicing fast and reliable.










TECHNICAL DATA A-DRY SERIES												
Туре	Connection IN/OUT		ninal e flow ¹⁾			Mass	Cartridge number					
	ш	m³/h	scfm	A [mm]	A* [mm]	B [mm]	B* [mm]	C [mm]	C* [mm]	kg	Hulliber	
A-DRY 06	G3/8"	6	3,5	339	404	288	490	100	120	10,5	2	
A-DRY 12	G3/8"	12	7,0	573	638	288	490	100	120	13,5	4	
A-DRY 24	G3/8"	24	14,1	1041	1106	288	490	100	120	19,0	8	
A-DRY 36	G3/8"	36	21,1	1509	1574	288	490	100	120	27,5	12	
A-DRY 60	G1/2"	60	35,3	1041	1106	370	582	148	170	45,0	8	
A-DRY 75	G1/2''	75	44,1	1275	1340	370	582	148	170	53,0	10	

1808

A-DRY 105	G1/2"		105	61,8			
Operating pres	sure range	4 to 16 bar					
Operating tem	Operating temperature range +1,5°C to +45°C						
Pressure dew p	ooints		-25°C / -40°C / -70°C				
Voltage, frequ	ency		230V, 50/60 Hz				
Power consum	ption		<30 W				
Protection class	is		IP 65				

¹⁾ Refers to 1 bar(a) and 20°C at 7 bar operating pressure, inlet temperature 35°C and pressure dew point at outlet -40°C.





70,0

CORRECTION FACTORS - F1													
Operating pressure [bar]	4	5	6	7	8	9	10	11	12	13	14	15	16
Operating pressure [psi]	58	72	87	100	115	130	145	160	174	189	203	218	232
Correction factor	0,63	0,75	0,88	1	1,13	1,25	1,38	1,50	1,63	1,75	1,88	2,00	2,13

2) In the event of operating pressures below 4 bar(g), an external instrument air supply must be provided.

CORRECTION FACTORS - F2											
Inlet temperature [°C]	25	30	35	40	45	50					
Correction factor	1,00	1,00	1,00	0,97	0,87	0,80					